

Winslow Farms – Moss Creek Pond System – **Depth Study Data** - May 17, 2008

(Ponds VII, VI, V, IV and III were full. Pond II was down ~2 inches, and I was down to inlet pipe.)

Pond Number	Location	Depth to Liner	Sediment	Comments
VII	1	2 ¾ feet	< 3 inches	Naiad 1 ft. below surface
	2	3 ½	< 3	.. 1 ½
	3	3 ¾	~ 4	
	4	3 ¾	~ 4	Very heavy Naiad Growth
	5	3 ½	~ 3	1 ft below surface
	6	3 ¾	3	same
	7	2 ½	4	same
	8.5	3 ¾	0	rock bottom
VI	9	3 ¾	6	mostly Naiad
	10	4	3	not in sight, but on bottom
	11	4 ¼	6
	12	3 ½	4
	13	3 ½	< 1
	13.5	2 ¼	12	Muck (black decayed weeds)
	14	3	< 1	Gravel bottom
V	15	4	15	Muck on bottom
	16	3 ¾	6
	17	3 ¼	18
IV	18	2 ½	8	Muck
	19	3 ¾	8	..
	20	3 ¾	12	..
	21	3 ¾	8	..
	22	3	12	..
	23	3	12	~30 ft from spillway
III	24	2 ¾	8	Muck
	25	2 ¾	12	..
	26	3 ½	12	..
	27	3 ½	15	..
	28	3 ¾	30	Muck with soil on top
	28.5	3	20
	29	3	18
	30	3	24
	30.5	2	12
II	31	2 ¾	6	Muck
	32	2 ½	6	..
	33	2 ½	6	..
I	34	3 ¼	8	Muck
	35	3 ¼	8	..
	36	3 ½	6	..
	37	3 ¼	0	..
	37.5	2 ½	6	..